Firmware Version History Release Note

Model Name	RUP2433AMI_D/1A1A24260112201
Location	3PD536F011A(RUP2433AMII)
Part	MAIN BD ASSY (2AAD536R0388)

Document No. / Rev.：QRC-L-016 / Rev. A

Status	Own	Frimware Vesion Description	Mark	Description of Changes
ES	Owen	RUP2433AMI_211221R0V01		First Release
MP	Owen	RUP2433AMI_231031R0V01		Modify OSD DVI 5V Output default from Off change to Pin 14 On.
MP	Owen	RUP2433AMI_240325R0V01		Modify OSD Gamma default from Cal change to DICOM1.
MP	Owen	RUP2433AMI_250808R0V01		modify Backlight to Max LED show Red and AC on led amber to
MP	Owen	RUP2433AMI_250808R0V01(045C-C15A)		1.modify PMW frequency from 200 Hz change to 240 Hz 2. Add EDID load ddcci .command.